



# উত্তরবঙ্গ কৃষি বিশ্ববিদ্যালয়

পুণ্ডিবাড়ী, কোচবিহার, পশ্চিমবঙ্গ-৭৩৬১৬৫

UTTAR BANGA KRISHI VISWAVIDYALAYA

P.O. PUNDIBARI, DIST. COOCH BEHAR, WEST BENGAL- 736165

ফোন/Phone: 03582-270588 (O)

ফ্যাক্স/Fax : 03582-270143

ইমেল/E-mail: [registrarubkv@gmail.com](mailto:registrarubkv@gmail.com)

[registrar@ubkv.ac.in](mailto:registrar@ubkv.ac.in)

নিয়ামক (ভারপ্রাপ্ত)

Registrar (Acting)

Ref.No. 398/UBKV/Est./(Veh-96)

Date:- 10/07/19

## Inviting Quotation

Sealed quotations are invited from the reputed Service centre/garage for repairing works of vehicle no. WB-63-1423 (Tata 709 midi bus). Interested service provider of vehicle may inspect the vehicle and submit their quotation on the following works (Copy enclosed).

The last date of submission of quotation is 23.07.2019 up to 2.00 PM and the same will be opened next working day at 3.00 PM.

Terms and condition:-

1. The quotation shall contain Trade license, Income Tax PAN no, GST registration.
2. Rate should be quoted with all applicable taxes and incidental charges.
3. The work should be completed within 7 days from the date of issue of work order.
4. The University reserves the right to accept or reject any or all quotation without assigning any reason what so ever.

Sd/-


Registrar (Actg.)

Ref.No. 398/UBKV/Est./(Veh-96)

Date:- 10/07/19

Copy forwarded for information:

1. Development Officer, UBKV.
2. Comptroller-in-Charge, UBKV.
3. In-Charge, Vehicle Section, UBKV.
4. University Mechanics, UBKV.
5. Notice Board.
6. Mr. Subhendu Das. He is requested to upload in the University website.

  
10/07/19  
Registrar (Actg.)



# উত্তরবঙ্গ কৃষি বিশ্ববিদ্যালয়

পুণ্ডিবাড়ী, কোচবিহার, পশ্চিমবঙ্গ-৭৩৬১৬৫

UTTAR BANGA KRISHI VISWAVIDYALAYA

P.O. PUNDIBARI, DIST. COOCH BEHAR, WEST BENGAL-736165

ফোন/Phone: 03582-270588 (O)

ফ্যাক্স/Fax : 03582-270143

ইমেল/E-mail: [registrar@ubkv.ac.in](mailto:registrar@ubkv.ac.in)

[registrar@ubkv.ac.in](mailto:registrar@ubkv.ac.in)

নিয়ামক (ভারপ্রাপ্ত)


Registrar (Acting)

Ref.No. ১৭৪ /UBKV/Est./(Veh-96)

Date:- 10/07/19

List of repairing job with material of vehicle no. WB-63-1423

1. Complete roof opening and repairing with new sheet, Turpel pasting.
2. Both side window glass channel opening, new channel fitting.
3. Body patch repairing.
4. Tie rod end: 04 nos.
5. Full wiring checkup and repairing.
6. Seat repairing (if required).

  
Registrar (Actg.)